Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

Database(s) EPA ID Number

437 OUTSIDE NY Spills S112809429
WSW 2832 WEST 24TH ST N/A

1/2-1 CONY ISLAND, NY

0.685 mi. 3617 ft.

Relative: SPILLS:
Higher Name: OUTSIDE

 Actual:
 Address:
 2832 WEST 24TH ST

 1 ft.
 City,State,Zip:
 CONY ISLAND, NY

 Spill Number/Closed Date:
 1214763 / 2013-01-19

 Spill Number/Closed Date:
 1214763

 Facility ID:
 1214763

 Facility Type:
 ER

 DER Facility ID:
 433329

 Site ID:
 478029

Site ID: 478029
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: Not reported

SWIS: 2401
Spill Date: 2013-01-19
Investigator: HRPATEL
Referred To: Not reported
Reported to Dept: 2013-01-19
CID: Not reported
Water Affected: Not reported

Spill Source: Commercial/Industrial

Spill Notifier: Other

Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Date Entered In Computer: 2013-01-19
Spill Record Last Update: 2013-03-04
Spiller Name: LAZZARI FF
Spiller Company: UNKNOWN

Spiller Address: 2832 WEST 24TH ST

Spiller Company: 999

Contact Name: LAZZARI FF

DEC Memo: "01/19/13-Hiralkumar Patel. 7:10 PM:- spoke with FDNY. oil leaked

onto asphalt street and concrete sidewalk only, from a temporary

boiler on street. FDNY completed cleanup. case closed.

02/22/13-Hiralkumar Patel. DEC Veronica forwarded email from Yelena Tkach from NYC Housing Authority, including cleanup document. Yelena Tkach Deputy Coordinator Technical Services Department NYC Housing

Authority 23-02 49th Ave, LIC, NY 11101 Tel.(718)707-5806

Cel.(917)579-2327 Fax.(718)707-5266 email: Yelena.Tkach@nycha.nyc.gov"

Not reported

Remarks: "asphalt affected only fuel pumped out - speedy dri used to clean up

up date - 03 gallons spilled - by - Yelena Tkach Depty cord. NYC

housing 718-707-5806"

All Materials:

 Site ID:
 478029

 Operable Unit ID:
 1227812

 Operable Unit:
 01

 Material ID:
 2225354

 Material Code:
 0001A

 Material Name:
 #2 fuel oil

Map ID	
Direction	Ч
Distance	

Distance Elevation Site EDR ID Number Database(s) EPA ID Number

MAP FINDINGS

Case No.: Not reported Material FA: Petroleum Quantity: 3.00 Units: G

Recovered: Not reported Oxygenate: Not reported